
City of Baltimore Wet Smoke and Dyed	Page 1 of 1	
Sewershed: Gwynns Falls Company: Savin		Date: <u>7/21/2009</u>
Test to be performed: Smoke Dyed Water X	Ground Condition: Dry ✓ Damp ☐ Wet ☐	Supervisor: <u>JAW</u>
Manhole_ID: S07K 002MH	Test ID: <u>D1032-009025</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Manhole	S07K009MH
0			Water Level	
184.6999969	10		Tap Factory Defective	JOL, From 3806 Old Frederick
184.8000031			Dye Test Visible	@ TFD - toilet
184.8000031			Dye Test Visible	@ TFD JOL - downspout
184.8000031			End of Survey	DYE TEST COMPLETED
184.8000031			Manhole	S07K002MH